MCU Wiring Diagram


Notes:

1) Dashed lines show data transmission - twisted wire pairs recommended for canbus, IP/IM and IN1/IN2 circuits.
2) Current Sensor pinouts shown for DHAB S/124 and S/137
3) Power circuits should be fused at the source based on wire gauge
4) CanTerm is a 120 Ohm 1/4 watt resistor connected near charger