




Anode Side (-) Negative M5 Terminal



Note: The BMS connecting plugs will fit on either end, so it's important to use the plug with the BLACK lead on the Negative Terminal side of the battery module.

Cathode Side (+) Positive M5 Terminal

